HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Addendum to Gunston Hall 10709 Gunston Road (State Rte. 242) Lorton Vicinity Fairfax County Virginia

HABS No. VA-141

Documentation: 30 sheets (1981, including site plans, plans, elevations,

sections, details)

7 ext. photos (1936, 1938)

30 ext. photos (1981) 34 int. photos (1981) 6 data pages (1941)

46 data pages (1981, 1982) 1 set of field records

Jack E. Boucher, Photographer, November 1981

Photos VA-141-1 through -7 were transmitted to the Library of Congress in 1936 and 1938.

VA-141-8 DISTANT VIEW OF HOUSE FROM NORTH

VA-141-9 GENERAL VIEW OF HOUSE AND GROUNDS FROM NORTH

VA-141-10 GENERAL VIEW OF HOUSE FROM NORTH (LAND) SIDE

VA-141-11 GENERAL VIEW OF EAST AND NORTH SIDES OF HOUSE

VA = 141 = 12EAST AND NORTH SIDES OF HOUSE

VA-141-13 NORTH SIDE OF HOUSE

VA-141-14 DETAIL OF PORCH ON NORTH (LAND) SIDE OF HOUSE

VA-141-15 DETAIL OF NORTH PORCH FROM NORTHEAST

VA-141-16 DETAIL OF NORTH PORCH FROM WEST

VA-141-17 DETAIL OF QUOINS, NORTHWEST CORNER OF HOUSE

VA-141-18 GENERAL VIEW OF HOUSE AND GROUNDS FROM NORTHWEST

VA-141-19 WEST SIDE OF HOUSE

VA-141-20 DETAIL OF QUOINS, SOUTHWEST CORNER OF HOUSE

VA-141-21 WEST AND SOUTH SIDES OF HOUSE



- VA-141-22 DISTANT VIEW OF HOUSE AND GARDENS FROM SOUTHWEST
- VA-141-23 DISTANT VIEW OF HOUSE AND GARDENS FROM SOUTHEAST
- VA-141-24 VIEW FROM SECOND FLOOR WINDOW OF HOUSE LOOKING SOUTH ACROSS GARDEN
- VA-141-25 VIEW FROM GAZEBO, LOOKING WEST ACROSS GARDEN
- VA-141-26 VIEW OF SOUTH (RIVER) SIDE OF HOUSE FROM GARDEN PATH
- VA-141-27 GENERAL VIEW OF SOUTH SIDE OF HOUSE
- VA-141-28 SOUTH SIDE OF HOUSE
- VA-141-29 DETAIL OF PORCH ON SOUTH (RIVER) SIDE OF HOUSE
- VA-141-30 DETAIL OF SOUTH PORCH FROM SOUTHEAST
- VA-141-31 SOUTH PORCH FROM EAST
- VA-141-32 GENERAL VIEW OF SOUTH AND EAST SIDES OF HOUSE
- VA-141-33 EAST SIDE OF HOUSE FROM SOUTHEAST
- VA-141-34 EAST SIDE OF HOUSE
- VA-141-35 VIEW SHOWING KITCHEN YARD AND EAST SIDE OF HOUSE
- VA-141-36 VIEW OF KITCHEN YARD AREA LOOKING NORTHWEST, SHOWING, FROM LEFT TO RIGHT, KITCHEN, WELL, DAIRY, AND WASH HOUSE
- VA-141-37 VIEW IN KITCHEN YARD LOOKING NORTHEAST, SHOWING, FROM LEFT TO RIGHT, KITCHEN, DAIRY, WELL, AND WASH HOUSE
- VA-141-38 VIEW FROM NOTH ENTRANCE OF CENTRAL PASSAGE TO SOUTH ENTRANCE
- VA-141-39 STAIRWAY IN CENTRAL PASSAGE
- VA-141-40 DETAIL SHOWING STAIR BRACKET OF STAIRS IN CENTRAL PASSAGE
- VA-141-41 SECOND FLOOR HALL AS SEEN FROM LANDING OF STAIRWAY IN CENTRAL PASSAGE
- VA-141-42 DOORWAY IN CENTRAL PASSAGE LEADING TO LITTLE PASSAGE
- VA-141-43 VIEW FROM SOUTH ENTRANCE OF CENTRAL PASSAGE TO NORTH ENTRANCE
- VA-141-44 DETAIL OF PENDANT BETWEEN ARCHES IN CENTRAL PASSAGE
- VA-141-45 NORTH ENTRANCE TO CENTRAL PASSAGE
- VA-141-46 VIEW LOOKING NORTHWEST IN DINING ROOM
- VA-141-47 LOOKING WEST IN DINING ROOM

VA-141-48	VIEW SHOWING WINDOWS ON NORTH WALL OF DINING ROOM
VA-141-49	DETAIL OF DINING ROOM WINDOWS
VA-141-50	DINING ROOM DOORWAY LEADING INTO PALLADIAN ROOM
VA-141-51	GENERAL VIEW LOOKING SOUTH IN PALLADIAN ROOM
VA-141-52	DETAIL OF PALLADIAN ROOM WINDOW
VA-141-53	GENERAL VIEW LOOKING WEST IN PALLADIAN ROOM
VA-141-54	DETAIL OF CUPBOARD ON WEST WALL OF PALLADIAN ROOM
VA-141-55	DETAIL OF CUPBOARD IN PALLADIAN ROOM
VA-141- 56	DETAIL SHOWING CEILING CORNICE IN PALLADIAN ROOM
VA-141-57	CLOSE-UP OF CEILING CORNICE IN PALLADIAN ROOM
VA-141-58	DETAIL OF PALLADIAN ROOM DOORWAY LEADING INTO DINING ROOM
VA-141-59.	DETAIL OF UPPER PORTION OF PALLADIAN ROOM DOORWAY
VA-141-60	DETAIL OF UPPER CORNER OF PALLADIAN ROOM DOORWAY
уа-141-61	CLOSE-UP OF TRIM SURROUNDING PALLADIAN ROOM DOOR
ya-141-62	DETAIL OF TRIM AT BASE OF PALLADIAN ROOM DOORWAY
VA-141-63	GENERAL VIEW LOOKING SOUTH IN LITTLE PARLOR
VA-141-64	GENERAL VIEW LOOKING EAST IN LITTLE PARLOR
VA-141-65	DETAIL OF CUPBOARD ON EAST WALL OF LITTLE PARLOR
VA-141-66	DETAIL OF DOOR IN LITTLE PARLOR LEADING TO SMALL PASSAGE
VA-141-67	VIEW LOOKING NORTH IN FIRST FLOOR CHAMBER
VA-141-68	VIEW IN FIRST FLOOR CHAMBER, LOOKING EAST
VA-141-69	DETAIL OF CUPBOARD ON EAST WALL OF FIRST FLOOR CHAMBER
VA-141-70	VIEW LOOKING SOUTHWEST IN SECOND FLOOR CHAMBER
VA-141-71	DETAIL OF CHIMNEY SUPPORT, EAST WALL OF BASEMENT

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO:

Virginia

HABS No. VA-141

(pg. 4)

GUNSTON HALL 10709 Gunston Road (State Route 242) Lorton Vicinity Fairfax County

VA-141-1 through VA-141-71 were previously transmitted to the Library of Congress.

INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Jack Boucher, Photographer, November 1981

VA-141-72 (CT)	GENERAL VIEW FROM NORTH (LAND) SIDE
VA-141-73 (CT)	GENERAL VIEW FROM NORTHEAST
VA-141-74 (CT)	GENERAL VIEW FROM NORTHWEST
VA-141-75 (CT)	DISTANT VIEW FROM GARDENS SHOWING SOUTH (RIVER) SIDE OF HOUSE
VA-141-76 (CT)	GENERAL VIEW FROM SOUTHEAST
VA-141-77 (CT)	GENERAL VIEW FROM SOUTHWEST
VA-141-78 (CT)	VIEWLOOKING SOUTH ACROSS GARDEN FROM SECOND FLOOR WINDOW
VA-141-79 (CT)	VIEW FROM GAZEBO, LOCATED SOUTHEST OF HOUSE, IN GARDEN

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS VA-141

ADDENDUM TO:
GUNSTON HALL
10709 Gunston Road
Lorton vicinity
Fairfax County
Virginia

Photographs HABS No. VA-141-1 to VA-141-79 were transmitted previously to the Library of Congress.

INDEX TO COLOR TRANSPARENCIES

Jack E. Boucher, photographer,

VA-141-80 (CT) View of the south porch looking from the east (duplicate of HABS No. VA-141-31)